

SAFETY RECALL

Extra UK Ltd Recalls Topeak Babyseat™ II Bicycle Carrier Seats

A child can place his or her fingers in the opening at the grab bar's hinge mechanism. When the consumer lifts the grab bar to remove the child from the seat, the child's fingertips can be caught in the hinge mechanism, posing a laceration and fingertip crushing hazard to the child.

AFFECTED HINGE MECHANISMS



RED LOCKING
LEVER APPEARS
ON ALL AFFECTED
MODELS

Consumers should immediately stop using the recalled carrier seats and call Extra UK to receive a free retro fit hinge cover kit

01933 672170 Ext 2

Further information can be found at www.extrauk.co.uk